5

Abstract of the Disclosure:

In a high-temperature fuel cell, the problem exists that a series electrical resistance rises while the high-temperature fuel cell is operating. This rise is caused by oxidation of the fuel-gas-side surface of the bipolar plate. Oxidation of this nature is largely suppressed by an oxidation buffer that is disposed in the fuel gas chamber and takes up the oxygen.

REL/kf